

THE REPUBLIC OF LIBERIA LIBERIA MARITIME AUTHORITY

22980 Indian Creek Drive, Suite 200 Dulles, Virginia 20166, USA Tel: +1 703 790 3434 Fax: +1 703 790 5655 Email: security@liscr.com Web: www.liscr.com

13 October 2023

Marine Advisory: 26/2023 (Supersedes Marine Advisory 24/2022)

Subject: Amendments to the Minimum Safe Manning Certificate

Reference: (a) Maritime Labour Convention (MLC), 2006

(b) Liberian Maritime Regulations RLM-108

(c) Marine Notices MAN-001 and MLC-004

To: Shipowners/Operators/Inspectors/Masters:

The following changes have been included:

1. Clarification provided on the location of ship's cook in the MSMC

Purpose

The purpose of this Marine Advisory is to inform shipowners, operators, inspectors and masters of amendments to the Minimum Safe Manning Certificate (MSMC) for ships.

Background

MLC, 2006 Regulation 3.2 and Standard A3.2 requires that ships with a manning of ten (10) or more crew shall be provided with a ship's cook trained, qualified and found competent for the position in accordance with requirements set out in the laws and regulations of Administration. RLM-108 section 10.315(2) and Marine Notice MLC-004 paragraph 5.2 set the training standards for ship's cooks. Furthermore, Standard A2.7.3 of MLC, 2006 requires the Administration to take into account all the requirements within Regulation 3.2 and Standard A3.2 concerning food and catering when determining manning levels.

Requirements

With effect from 1 December 2022, the Administration will include the provision for a ships' cook in the Special Requirements or Conditions section of the new MSMC for ships with a manning of 10 or more crew. All other MSMC shall include the provision for a ship's cook in the Special Requirements or Conditions section at the next reissuance of the MSMC but no later than 31 December 2023.

Ships' cooks shall be trained and certified in accordance with the standards noted under "Background" above and Regulation VI/I of STCW. The Administration will also issue Special Qualification Certificates where the seafarer serving as ship's cook meets the requirements.

Clarification

It should be noted that the ships cook is not included as part of the ship's complement in the section under STCW Regulation, since the ship's cook is not required under SOLAS or STCW, but is required under the ILO MLC, 2006.

To apply for reissuance of MSMC, please contact <u>VesselCertificates@liscr.com</u> and for application of a ship's cook SQC, please contact <u>Seafarers@liscr.com</u>.

Questions regarding this instruction should be referred to ${\bf RegsandStandards@liscr.com}$ or you may call +1-703-790-3434.

* * * * *